

(Sheet 4)

Induction Motor (I.M)

$P_{out} = 40 \text{ hp}$, 3300 V , 50 Hz , 4 poles, 3-ph star connected induction motor, slip = 2%. P.f = 0.8 lag at full load
stator copper losses, core losses and mechanical losses are:
 1000 W 1500 W 1200 W

(1 hp = 746 W). Find at full load:

- ① motor speed ② The line current ③ rotor copper loss
④ η %

$$N_s = \frac{120 f}{P} = \frac{120 \times 50}{4} = 1500 \text{ rpm}$$

$$\therefore \text{slip} = 2\% \quad \therefore 0.02 = \frac{N_s - N}{N_s} \quad \text{or } \underline{N = N_s(1-s)}$$


$$\therefore 0.02 \times 1500 = 1500 - N$$

$$\therefore \boxed{N = 1470 \text{ rpm.}} \quad \# \text{ ①}$$

$$N = N_s(1-s)$$

$$\therefore P_{in} = 3 V_L I_L \text{ P.f}$$

والجواب إجابتي I_L لا بد من حساب P_{in}
 من خلية الفيل



$$\therefore P_m = P_{mech} + P_{out}$$

$$\therefore P_m = 1200 + (40 \times 746) = 31040 \text{ W}$$

$$1 : S : 1 - S$$

$$\therefore P_g (1 - S) = P_m \quad \therefore P_g = \frac{P_m}{1 - S}$$

$$\therefore P_g = \frac{31040}{1 - 0.02} = 31673.47 \text{ W}$$

$$P_{in} = [P_{\text{stator}} + P_{\text{core}}] + P_g$$

$$\therefore P_{in} = [1000 + 1500] + 31673.47$$

$$\therefore P_{in} = 34173.47 \text{ W}$$

$$\sqrt{3} V_L I_L P.F. \Rightarrow P_{in} = 3 V_L I_L P.F.$$

$$\therefore 34173.47 = 3 \times \frac{3300}{\sqrt{3}} \times I_L \times 0.8$$

$$\boxed{I_L = 7.4735 \text{ A}} \quad \# (2)$$

لنفسه جعل الجهد الخطي
phase
من توصيلة star
الآلة والخط line

$$\therefore P_{cu2} = S \cdot P_g$$

$$\therefore P_{cu2} = 0.02 \times 31673.47 = \boxed{633.47 \text{ W}} \quad \# (3)$$

$$\eta \% = \frac{P_{out}}{P_{in}} \times 100 = \frac{40 \times 746}{34173.47} \times 100$$

$$\boxed{\eta \% = 87.32\%} \quad \# (4)$$


3-ph, 500 V, 50 Hz, 6 poles, star connected I.M develops (net o/f = 20 hp) at 950 rpm with P.f = 0.85 lag, $P_{mech.} = 1 \text{ hp}$. Stator losses are 1500 W (neglect core losses). Find:

- ① slip ② rotor copper losses ③ line current

$$\therefore N_s = \frac{120 f}{P} = \frac{120 \times 50}{6} = 1000 \text{ rpm}$$

$$\therefore N = 950 \text{ rpm} \quad \therefore S = \frac{N_s - N}{N_s} = 0.05$$

$$\therefore \boxed{S = 5\%} \quad \# \text{ ①}$$



$$\therefore P_m = P_{mech.} + P_{out} = (1 \times 746) + (20 \times 746)$$

$$\therefore P_m = 15666 \text{ W}$$

$$\therefore P_g : P_{cu2} : P_m$$

$$1 : S : 1 - S$$

$$\therefore P_{cu2} \times (1 - S) = S \times P_m$$

$$\therefore P_{cu2} = P_m \frac{S}{1 - S} = 15666 \times \left(\frac{0.05}{1 - 0.05} \right)$$

$$\therefore \boxed{P_{cu2} = 824.526 \text{ W}} \quad \# \text{ ②}$$

$P_{in} = \text{stator \& Ig losses}$

$$\therefore P_g (1-s) = P_m \quad \therefore P_g = \frac{P_m}{1-s}$$

$$\therefore P_g = \frac{15666}{1-0.05} = 16490.526 \text{ W}$$

$$\therefore P_{in} = 1500 + 16490.526 = 17990.526 \text{ W}$$


$$\therefore P_{in} = 3 V_1 I_1 \text{ PF}_1$$

$$\therefore I_1 = \frac{P_{in}}{3 \times V_1 \times \text{PF}_1} = \frac{17990.526}{3 \times \frac{500}{\sqrt{3}} \times 0.85}$$

$$\therefore \boxed{I_1 = 24.44 \text{ A}} \quad \# (3)$$

3-ph, 50 Hz, 80 hp, 4 Pole, star connected I.M has $\eta = 0.9$
 core losses = 1500 W, stator copper loss = 2000 W, rotor copper
 losses = 1400 W. Find:

- ① i/p Power (P_{in}) ② Airgap Power (P_g) ③ shaft speed (N)



$$P_{out} = 80 \times 746 = 59680 \text{ W}$$

$$\eta = 0.9 = \frac{P_{out}}{P_{in}} \therefore P_{in} = \frac{59680}{0.9} = \boxed{66311.11 \text{ W}} \quad \# (1)$$

$$P_{in} = [P_{\text{stator copper}} + P_{\text{core}}] + P_g$$

$$66311.11 = [2000 + 1500] + P_g$$

$$\boxed{P_g = 62811.11 \text{ W}} \quad \# (2)$$

$$P_g : P_{\text{rotor copper}} : P_m$$

$$1 : s : 1 - s$$

$$P_g \cdot s = P_{\text{rotor copper}}$$

$$s = \frac{P_{\text{rotor copper}}}{P_g} = \frac{1400}{62811.11} = \boxed{0.02}$$

$$\boxed{\text{slip} = 2\%}$$

$$N_s = \frac{120f}{p} = \frac{120 \times 50}{4} = 1500 \text{ rpm}$$

$$\frac{N_s - N}{N_s} = s$$

$$N = N_s(1 - s) = \boxed{1466.56 \text{ rpm}} \quad \# (3)$$

(5)

3ph, 400V, 50Hz, 6 pole star connected I.M

Core losses = 500W; $\omega_s = 2\pi \times 50$; $L_m = 2$ mH; $\omega = 1$ rad/s

3ph star connected, 50Hz; 6 pole, 380V I.M running at 150 rpm has net o/p torque of 25 N.m. If the stator copper losses and Core losses = 350W, mech. losses = 250W


i/p Power factor (Pf_1) = 0.7 lag Find:

(1) The slip (2) rotor copper losses (3) P_g (4) line current (I_L) (5) η :

-jsl-

$$N_s = \frac{120 f}{P} = \frac{120 \times 50}{6} = 1000 \text{ rpm}$$

$$S = \frac{N_s - N}{N_s} = \frac{1000 - 950}{1000} = 0.05 \quad \# \text{ (1)}$$



$$P_{out} = \omega \times T_{out} = \frac{2\pi N}{60} \times T_{out}$$

$$P_{out} = \frac{2\pi \times 950}{60} \times 25 = 2487.1 \text{ W}$$

$$P_m = P_{mech} + P_{out} = 250 + 2487.1 = 2737.1 \text{ W}$$

$$P_g : P_{cu2} : P_m$$

$$1 : S : 1-S$$

$$(1-S) \times P_{cu2} = S P_m$$

$$P_{cu2} = P_m \times \frac{S}{1-S} = 2737.1 \times \frac{0.05}{1-0.05}$$

$$P_{cu2} = 144.05 \text{ W} \quad \# \text{ (2)}$$

$$P_{cu2} = P_g \times S$$

$$\therefore P_g = \frac{P_{cu2}}{S} = \boxed{2881.151 \text{ W}} \quad \# (3)$$

$$\therefore P_{in} = P_g + [P_{\text{stator upper}} + P_{\text{core}}] = 2881.151 + [350]$$

$$\therefore P_{in} = \boxed{3231.151 \text{ W}}$$

$$\therefore P_{in} = \sqrt{3} V_1 I_1 \text{ P.f.}_1$$

$$\therefore I_1 = \frac{P_{in}}{\sqrt{3} V_1 \text{ P.f.}_1} = \frac{3231.151}{\sqrt{3} \times 380 \times 0.7}$$


$$\therefore \boxed{I_1 = 7.013 \text{ A}} \quad \# (4)$$

$$\therefore \eta\% = \frac{P_{out}}{P_{in}} \times 100 = \frac{2487.1}{3231.151} \times 100$$

$$\therefore \boxed{\eta\% = 76.97\%} \quad \# (5)$$

3 ph, 20 hp, 500 V, 50 Hz, 6 poles star connected I.M running at 950 rpm with $P_{f1} = 0.85$ lag. mech. losses = 1 hp, stator copper losses = 1500 W, Core losses = 500 W. Find:
 (1) Rotor Copper losses (2) Line Current I_L (3) $\eta\%$

$P_{out} = 20 \times 746 = 14920 \text{ W}$



$P_m = P_{mech} + P_{out} = (1 \times 746) + 14920 = 15666 \text{ W}$

$\therefore P_g : P_{m2} : P_m$
 $1 : s : 1-s \quad \therefore P_{m2} (1-s) = P_m \times s$

$s = \frac{N_s - N}{N_s} \quad N_s = \frac{120 f}{P} = \frac{120 \times 50}{60} = 1000 \text{ rpm}$

$\therefore s = 0.05$

$\therefore P_{m2} = P_m \frac{s}{1-s} = \boxed{824.526 \text{ W}} \quad \# \text{ (1)}$

$\therefore P_{m2} = s P_g$

$\therefore P_g = \frac{P_{m2}}{s} = 16490.526 \text{ W}$

$\therefore P_{in} = [P_{stator \text{ copper}} + P_{core}] + P_g = (1500 + 500) + 16490.526$

$\therefore P_{in} = 18490.526 = \sqrt{3} \times V_L \times I_L \times P_{f1}$

$\therefore I_L = \frac{18490.526}{\sqrt{3} \times 500 \times 0.85} = \boxed{25.1188 \text{ A}} \quad \# \text{ (2)}$

$\therefore \eta\% = \frac{P_{out}}{P_{in}} \times 100 = \frac{14920}{18490.526} \times 100 = \boxed{80.7\%} \quad \# \text{ (3)}$